



GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program June 28, 2012

Reviewed: 

Mine Name: Last Chance 25 & 26	Permit Number: M/015/0061
Operator Name: Western Clay Company	Inspection Date: April 21, 2011
Inspector(s): Wayne Western	Time: 3:30 – 3:50 PM
Other Participants: none	Mine Status: ACT
Weather Condition: Hot and clear skies	Last Inspection: April 21, 2011
Bond Renewal Date: 07/26/2016	Bond Amount: \$55,600
Surface Ownership: BLM	Mineral Ownership: BLM
Last Year of Production: 2009	Acreage: 10 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Bond/Bond Release	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Annual Fees	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Annual Report	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This was a routine inspection.

Inspection Summary:

The bond, permit fees and annual reports are up to date.
The mine is a surface mine and does not have shafts or adits.
The area appears stable and there is no sign of erosion problems.
Road are stable.

Conclusions and Recommendations:

The site is stable. The Division should continue to monitor the site.

Directions to Site:

Inspector's Signature _____

WHW:

cc: (OPERATOR)

Christopher_Conrad@blm.gov

O:\M015-Emery\M0150061-Lastchance\inspection\INSP-06272012.doc



Roads and mine area.



Loadout area